

## r24.0.3 Changelog

+-----+  
| r24.0.3 Release - 155917  
+-----+

Release day 22nd March 2023

**For any vx 4+ users please refer to this advisory before using this Designer software version' and link to the advisory on the website.**

## Fixes

- DSOF-21119 - GPU fan speed is now programmatically set on vx4+
- DSOF-23479 - Fixed Access Violations that occurred when a mapping indirection is added to a slot in the Bank Editor, and when a new indirection is subsequently attempted
- DSOF-23569 - SDI- IPVFC: VX4 output is no longer tearing or not outputting
- DSOF-23726 - IPVFC - Addressed a 10 second sleep that was causing 'Timed out waiting for output mode change' error notification